

Spinner Assembly: Qualitative Testing



Results:

Noticeable signal distortion appears at frequencies > 1 KHz

Significant signal distortion appears at signal frequencies > 1 MHz

Conclusion:

5 MHz Sine

Wave serial
Transmitted Signal

Problem
Input

minima
Difference

