

John Hartigan / Site 6

14 Nov 2008

### Session set-up

#### Equip

RS laser level  
Sharp 9000 XC-9000  
TRK 9-126 HSBH vidastop

jbuck  
211325


Dan's camera VHS-400  
VCR  
Fluk 179  
284 laser mark

} 6m 42 sec → H5 H6 50513 SN  
00:00:00 → MET 0403445  
jbuck


Trial 1

H5 / H6  
- 5:03 / - 1m 19.22

drop on edge




Cracked slightly



Trial 2

7:57 / 11:10:00



problem w/ VHS!

Trial 3  
Trial 4  
Trial 5  
Trial 6  
Trial 7


Leak  
Leak on one side only  
did not BREAK!

- 01:18.24  
- 1:53:17  
- 2:36:06  
- 3:09:07  
- 3:28:03

John Hawkins / Stage 6

14 Nov 2008

Schieren light same



RED: Rosolux #200 / Stormo  
 GR: #89 Moss GREEN  
 BL: #70 Nile Blue (X2)  
 Yaka: #310 Dark Red (X2)

Schieren lamp "1"


Prod 8: 2x8" glass

- 4:21:28

Prod 9: ES mirror

- 6:31:26

relation grid with water & heat & screener.



47,058 eps

5 ps  
3 ps  
Exp  
FDR

43,422 f  
256 x 128  
Zoom 1  
pattern  
px

0.919 sec Duration

Prod 1

Glass broken from heat stress (unexp'd)

Prod 2

3rd gun on broken piece - no action


Prod 3

1st pattern & heat  
area f/2.4 (PNR)

Prod 4 & T5

f/5.6

Trail Z



58  
 47,000 fms  
 5 fms Esp  
 3 fms EIM  
 48,242  
 total fms  
 256x128  
 0.7075

Nikon 2  
 50mm

DO NOT BREAK!